

Consumer Product Safety Commission (CPSC) Lead Recall: Boyro Baby Walkers

DATE:	7/14/2025
TO:	Health Alert Network
FROM:	Debra L. Bogen, M.D., FAAP, Secretary of Health
SUBJECT:	Consumer Product Safety Commission (CPSC) Lead Recall: Boyro Baby Walkers
DISTRIBUTION:	Statewide
LOCATION:	N/A
STREET ADDRESS:	N/A
COUNTY:	N/A
MUNICIPALITY:	N/A
ZIP CODE:	N/A

This transmission is a “Health Advisory” and provides important information for a specific incident or situation; may not require immediate action.

**HOSPITALS:** PLEASE SHARE WITH ALL MEDICAL, PEDIATRIC, NURSING AND LABORATORY STAFF IN YOUR HOSPITAL; **EMS COUNCILS:** PLEASE DISTRIBUTE AS APPROPRIATE; **FQHCs:** PLEASE DISTRIBUTE AS APPROPRIATE; **LOCAL HEALTH JURISDICTIONS:** PLEASE DISTRIBUTE AS APPROPRIATE; **PROFESSIONAL ORGANIZATIONS:** PLEASE DISTRIBUTE TO YOUR MEMBERSHIP; **LONG-TERM CARE FACILITIES:** PLEASE SHARE WITH ALL MEDICAL, INFECTION CONTROL, AND NURSING STAFF IN YOUR FACILITY.

### Summary

- On June 26, 2025, Boyro Baby Walkers, model number US-B01, were recalled because they contain levels of lead that exceed the federal lead content ban. It also violates the federal safety standard for infant walkers and could pose a serious risk of injury or death due to a fall.
- The plastic walkers were sold in black, blue, and gray with five levels of height adjustments. They have a black or gray rotating seat, a matching footpad, six wheels and four removable toys (an owl, a flower, an arch with a ball and a three-button panel that plays music and lights up.) “Ready To Ride” appears on a label on one of the walker’s legs and the height-adjustment buttons are on another leg. “Boyro Baby” and the model number are printed on the tracking label, located under the seat cushion.
- The recalled baby walkers’ brake pads contain levels of lead that exceed the federal lead content ban.
- They were sold exclusively online at Amazon.com from August 2024 through December 2024 for between \$70 and \$90.
- Consumers should stop using and disassemble the recalled baby walkers immediately and contact Boyro Baby for instructions on receiving a full refund. Consumers will be asked to destroy the disassembled baby walker and email three photos of the destroyed product to boyrobaby@outlook.com. Once the three photos have been received, Boyro Baby will issue a refund. Boyro Baby and Amazon are contacting all known purchasers directly.
- Please visit the [Consumer Product Safety Commission’s website](#) to view the lead recall and share it with your networks.
- For more information on childhood lead exposure in Pennsylvania, visit [Lead Poisoning \(pa.gov\)](#), contact [your local health department](#) or contact DOH at 1-877-PA-HEALTH if you have any questions.

## Background

On June 26, 2025, Boyro Baby Walkers, model number US-B01, were recalled because the baby walkers' brake pads contain levels of lead that exceed the federal lead content ban, posing a health hazard to children. The walkers also violate the federal safety standard for infant walkers because they can fit through a standard doorway and fail to stop at the edge of a step as required, posing a risk of serious injury or death due to a fall hazard.

Approximately 1,500 units were sold in the U.S. exclusively online at Amazon.com from August 2024 through December 2024 for between \$70 and \$90.

The plastic walkers were sold in black, blue and gray with five levels of height adjustments. They have a black or gray rotating seat, a matching footpad, six wheels and four removable toys (an owl, a flower, an arch with a ball and a three-button panel that plays music and lights up.) "Ready To Ride" appears on a label on one of the walker's legs and the height-adjustment buttons are on another leg. "Boyro Baby" and the model number are printed on the tracking label, located under the seat cushion.

The retailer is Hangzhou Christine Trading Co. Ltd., dba Boyro Baby, of China.

Consumers should stop using and disassemble the recalled baby walkers immediately and contact Boyro Baby for instructions on receiving a full refund. Consumers will be asked to destroy the disassembled baby walker and email three photos of the destroyed product to [boyrobaby@outlook.com](mailto:boyrobaby@outlook.com). Once the three photos have been received, Boyro Baby will issue a refund. Boyro Baby and Amazon are contacting all known purchasers directly. Consumers should dispose of the recalled walkers by contacting the local household hazardous waste collection program. Please bag and label these parts as hazardous waste, and do not put the walkers into the regular trash collections.



Lead exposure can have serious health consequences, especially for children and pregnant women. Lead is ubiquitous in the environment, and unfortunately, we cannot see, taste or smell it. Lead is much more harmful to children and during pregnancy because it can affect a child's developing nervous system and brain.

## Recommendations associated with this recall

- Review recall information including pictures of the specific item being recalled. This information is available on the [CPSC's website](#).
- Health care providers should raise awareness about the recalled products among parents.
- Encourage parents to stop using and disassemble the recalled baby walkers immediately and contact Boyro Baby for instructions on receiving a full refund. Consumers will be asked to destroy the disassembled baby walker and email three photos of the destroyed product to [boyrobaby@outlook.com](mailto:boyrobaby@outlook.com). Once the three photos have been received, Boyro Baby will issue a refund. Boyro Baby and Amazon are contacting all known purchasers directly.
- Consider blood lead testing for children or those who are pregnant or lactating if they are exposed to these and other lead sources.

- Children enrolled in Medicaid are required to get tested for lead at ages 12 and 24 months or age 24–72 months if they have no record of ever being tested. All children should be tested if they are at risk for lead exposure, which includes children who live or spend time in a house or building built before 1978, are from low-income households, are immigrants, refugees, or recently adopted from lower income countries, or live or spend time with someone who works with lead or has hobbies that expose them to lead.
- Laboratories and health care providers are required to report all blood lead test results, regardless of the lead level, for persons under 16 years of age to DOH through Pennsylvania's electronic disease surveillance system, PA-NEDSS.

### Additional resources on childhood lead exposure

- [Lead Poisoning \(pa.gov\)](#)
  - [Elevated Blood Lead Level Resources \(pa.gov\)](#)
  - [Lead Poisoning FAQ \(pa.gov\)](#)
- [Childhood Lead Poisoning Prevention Program | CDC](#)
- PA DOH lead information 1-800-440-LEAD

**For questions, please call your local health department or DOH at 1-877-PA-HEALTH (877-724-3258).**

Individuals interested in receiving future PA-HANs can register at <https://ondemand.mir3.com/han-pa-gov/login/>.

Categories of Health Alert messages:

**Health Alert:** conveys the highest level of importance; warrants immediate action or attention.

**Health Advisory:** provides important information for a specific incident or situation; may not require immediate action.

**Health Update:** provides updated information regarding an incident or situation; unlikely to require immediate action.

This information is current as of July 14, 2025 but may be modified in the future. We will continue to post updated information regarding the most common questions about this subject.